



001.Enter Setup



002.Restore Default Settings

Interface Settings : Direct USB HID



003.Disable Cable Auto-Detection



004.HID PCAT (US)



005.0x06



006.0x04



007.Validate



008.Update